

Tech Note 066

Subaru Pull Type Clutch Shudder

Ref: TN066

Issue Date: Feb 17

Issue Number: 2

Important Information

Before fitment of new clutch, inspect clutch fork contacts for wear as shown in diagram below & replace, if necessary, with:

EXEDY Part No:

CF02 for 5 Speed

CF10 for 6 Speed

Failure to do so may result in clutch shudder during operation of new clutch.

