

## Fitment instruction for CSC2382

Ref: TN059

Issue date: June 2013

Issue number: 1

### Important Information

The red tab fitted to this Concentric Slave Cylinder should not be removed prior to mounting the cylinder to the transmission.

Removal of the tab prior to fitment can result in damage to the internal seal (not the separate o-ring) which causes the cylinder to leak fluid.

