

# Tech Note 056

## Clutch Release Mechanism Wear / Noise

Ref: TN056

Issue Date: July 2016

Issue Number: 2

### Important Information

In this application, wear or inadequate lubrication of the release mechanism components often results in a noise (squeak or squeal) being emitted from within the bell-housing which is generally misdiagnosed as a release or spigot bearing fault.

It is essential clutch forks and pivot balls are cleaned, properly inspected and worn items replaced.

