

## Technical Information (Slave Cylinder) Holden / Isuzu

Ref: TN075

Issue date: Dec 2015

Issue number: 2

It has been found that the solenoid fitted to the rear of the clutch slave cylinder in these vehicles can often fail, therefore restricting the flow of hydraulic fluid to and from the master cylinder.

Failure to check for or replace a faulty slave cylinder may result in clutch slip, clutch non-release and premature clutch failure.

Replacement cylinders can be purchased from your EXEDY distributor, part number to order CS001.

