

Holden Cruze Hydraulic Failure

Ref: TN107

Issue Date: Oct 2019

Issue Number: 1

Important Information!

The rubber grommet (pictured below) may detach from the original concentric slave cylinder (CSC) whilst being disconnected from the bleeder fitting in this application.

Failure to identify and remove the grommet prior to fitment of the replacement cylinder will often result in complete hydraulic failure due to over-pressurisation of the CSC.

