

**Ford Ranger Mazda BT50 2.5L/3.0L Turbo crankshaft
bolts tightening torque**

Ref: TN043

Issue date: 14 Oct 2014

Issue number: 2

**FMK-7740SMF / FMK-7740SMFHD /
FMK-7740SMFHDB**

Replacement crankshaft bolts are supplied with these clutch kits and should be tightened to the following torque specification: 156 Nm +/- 5 Nm