

BMW Release Bearing to Clutch Fork Installation

Ref: TN081

Issue date: Dec 2014

Issue number: 1

CAUTION

In this application it is possible to incorrectly fit the clutch release bearing to the clutch fork.

The clutch release bearing must be installed with the taller (33.5mm) bearing pivot surfaces contacting the clutch fork.

Failure to correctly install the release bearing will result in either clutch non-release or difficult gear selection.

