

Hyundai Clutch Fork to Release Bearing Orientation

Ref: TN089

Issue date: Dec 2015

Issue number: 1

Due to the design of the release bearing in this application, the clutch release fork can only be properly fitted to the bearing from one direction. Please refer to the below image in order to identify the correct fork to bearing orientation.

Failure to follow these instructions will result in damage to the release bearing and unsatisfactory clutch operation.

