

Tech Note 076

Hyundai Pull Type Clutch

Ref: TN076

Issue date: August 2014

Issue number: 1

Prior to installation, the clutch plate facing will not sit flat on the surface of the clutch pressure plate due to contact with the pull type bearing retainer.

This is deemed acceptable in this application and clearance from the retainer occurs after affixing the clutch cover assembly to the flywheel.

