

Holden Alloytec V6 Needle Roller Pilot Bearing

Ref: TN105

Issue date: Jun 2019

Issue number: 1

When installing this clutch into the Holden Colorado, please ensure to insert the needle roller bearing into the crankshaft.

(Note, this part is not required in Holden Commodore applications).

