

Holden Commodore V6 VSII - VY flywheel installation

Ref: TN039

Issue date: 07 Jun 2010

Issue number: 1

The flywheel included in this kit has a balance mass which compensates for the internal “Out of Balance” moment within the Holden V6 engine, as fitted to VSII – VY model series

Please note the following during flywheel installation:

- ***the orientation of the flywheel to crankshaft is critical***
- ***one (1) of the flywheel to crank holes is offset by a minor amount***
- ***when installing the flywheel, introduce & tighten each bolt by hand. DO NOT USE AN IMPACT GUN as it is possible to locate the flywheel 180 degrees out. Failure to position the flywheel correctly will result in chronic vibration!***