

Tech Note 086

Subaru Flex Plate Flywheel

Ref: TN086

Issue date: Oct 2015

Issue number: 1

Please refer to the information below in order to identify the correct Flex Plate Flywheel kit for your vehicle.

Fitment of an incorrect Flex Plate Flywheel may result in damage to the engine timing tone wheel (located between the flywheel and crankshaft) and the vehicles crank angle sensor.

- For vehicles fitted with **EJ** series engine codes:

Use EXEDY kit No. FJK-7626SMF

- For vehicles fitted with **FB** series engine codes (tone wheel between flywheel and crankshaft):

Use EXEDY kit No. FJK-8635SMF