

# Tech Note 041

## Transportation Clips

Ref: TN041

Issue date: 18 Jun 2010

Issue number: 1

This kit may contain a cover assembly that has clips securing the pressure plate to the cover pressing during transport.

It is imperative that these clips (three off) be removed prior to the assembly being bolted to the flywheel. Technique-Depress the diaphragm fingers under a drill press to release the clips.

Failure to remove the clips will result in major damage to the bell housing.

Should you have any queries regarding this technote, please contact your local EXEDY distributor for further details.

