

Tech Note 068

Setting of Volvo Twin Plate Centralisers

Ref: TN068

Issue date: Feb 2014

Issue number: 1

Upon fitment of the centralisers in this kit, it is essential that there is a gap between the underside of the centraliser slider and the bottom of the locating slot in the pressure plate casting (Please see below for visual reference).

Failure to provide this gap will result in clutch non-release and gear selection issues.

