

Daewoo Lanos, Leganza, Nubira, Cielo, Kalos & Espero Clutch Release Shaft

Ref: TN021

Issue date: 10 Aug 2006

Issue number: 3

WITH HYDRAULIC RELEASE MECHANISM

Please be advised that the Clutch Release Shaft and Lever assembly has a history of failure in that the weld securing the lever to the cross shaft is suspect.

It is recommended that the shaft be inspected and replaced if the lever is found to be in any position other than in line with the detent slot.

A new shaft can be purchased from your EXEDY distributor, EXEDY part number RS01.

