

## CSC2365 Installation Instruction Note

Ref: TN031

Issue date: 21 Nov 2008

Issue number: 1

When replacing a concentric slave cylinder, please follow the instructions below to ensure correct operation -

- 1 All grease or dust contamination must be removed from inside the bell housing.
- 2 All retaining bolts must be located and torqued to the manufacturer's specification.
- 3 An "O" ring is located between the CSC and transmission and it must be replaced to prevent fluid leak and hence clutch non-release.
- 4 The cylinder should be installed without grease and do not clean the cylinder with solvent.
- 5 Use only virgin Dot 4 or the manufacturers recommended brake fluid.

