

## Citroen / Peugeot Pull Type Clutch Installation

Ref: TN073

Issue date: May 2014

Issue number: 1

### CAUTION!

The clutch release fork can only be properly installed when the top and bottom of the clutch release bearing are correctly positioned as pictured below.

Failure to do so may result in unsatisfactory pedal feel or damage to the release bearing.

