

## Installation of Mercedes and Volvo Twin Clutch

Ref: TN061

Issue date: 25 July 2013

Issue number: 1

After mounting this clutch to the flywheel it is essential that the centralizers are correctly located to limit the movement of the intermediate pressure plate during operation. This is achieved by tapping down the centralizers using an appropriate drift & hammer (as pictured below).

Failure to carry out this procedure may result in clutch non release issues.

