

Discontinued Ford Focus Concentric Slave Cylinder

Ref: TN077

Issue date: Sep 2014

Issue number: 1

The Concentric Slave Cylinder with 'in line' bleeder has been discontinued (Old Design). The replacement cylinder supplied by EXEDY incorporates a bleed nipple in the body of the cylinder. When fitting this new cylinder, a replacement hydraulic line (EXEDY Part No. HDL02) will be required for vehicles with a build date pre 02/2007.

